



EFFECTIVE LINE CLEANING



**WEAR GLOVES AND GOGGLES
AT ALL TIMES**



**ALWAYS FOLLOW MANUFACTURER'S SAFETY
GUIDELINES ON THE DETERGENT CONTAINER**



**TURN OFF COOLERS AND FLUSH PIPES
THROUGH WITH WARM WATER**




DRAW THROUGH 2 PINTS PER TAP



SOAK FOR 10 MINS



**REPEAT DRAW OFF AND SOAK
A FURTHER TWO TIMES**



**FLUSH THROUGH WITH
FRESH CLEAN WATER**

**FLUSH FOB DETECTORS THROUGH.
BLEED VALVES AT EACH STAGE**

DELIVERING GREAT BEER TOGETHER

